

## Photographs of good & poor control practice



Dry sweeping (even though RPE is worn) this could have been undertaken using a shovel loader (dry sweeping was subsequently stopped by the company)



Tipping hall where waste is transferred to sorting conveyor by mechanical shovel loader (cab is HEPA filtered and subject to maintenance by hire company every 100hrs of use)



**Cleaner blowing down floor using compressed air (this is simply displacing the dust/debris not cleaning) and is worse than dry brushing!**



**Steam washer to clean heavy plant used in waste/compost tipping and processing halls**



Fully enclosed auger transporting food waste